

Revision History:

Y/M/D	Author	AndroidViewerHD version
2015/07/24	Vivian	5.3.1022.28
2015/06/04	Chris	5.3.1022.27
2015/03/11	Chris	5.3.1022.26
2015/01/09	Chris	5.3.1022.25
2014/09/26	Chris	5.3.1019.22
2014/08/08	Chris	5.3.1017.19
2014/06/06	Chris	5.3.1016.17
2014/05/15	Chris	5.3.1013.16
2014/04/07	Chris	5.1.109.13
2013/12/19	Chris	4.7.107.9
2013/10/29	Chris	4.5.106.7
2013/10/18	Chris	4.3.104.6
2013/08/27	Stanley Lin	4.1.100.4

Ps The latest update should be listed on the top



Release Notes

Product	AndroidViewerHD
Version	5.3.1022.28
Introduction	Official Release
Hardware Compatibility	Android system Mobile, PAD
Operating Systems	Android 2.3.5 above
Compatibility List	<ol style="list-style-type: none"> 1. NVR/DVR: E, P series, IWH series, EH series, NV series 2. Camera: SF2121H-R, SF2121H-BHR, SF2121H-DVR, FB2027-1/(E), FB2027-2,FB2027-3/(E), FB3027, FB2028-T1/(E), FB2028-T2/(E), FB2028-TM/(E), FV2028-T/(E),FV2028-TM/(E), FX2000/(E), FB3028-RT1/(E), FB3028-RT2/(E), FB3028-RTM/(E), FD2020/(E), FD2020-M/(E), FD3020, FD3020-M, FV2028/(E), FV3028, FV3028-RT/(E), FV3028-RTM/(E), FX3000-R/(E), SF2012H, SF2012H-B, SF2012H-C, SF2012H-D, SF2012H-DV, SF2111H-BR, SF2111H-DR, SF2111H-DVR, SF2111H-R, FV1306, FV2006, FC1320-P, FC1320-PW, FC2020-P, FC2020-PW, SD1306, FD1020, FC1020-P, FC2020-P1,FC1000,FC1000-1,FD2000-1,FD2000-2,FD2000-3,SD2026, FV2006-1,FV2026-M,FB1026,FB2026,FB2026-M,FB2026-F,FD2020-1, FD2020-F.
Change Log	<ol style="list-style-type: none"> 1. Support New cameras: FC1000,FC1000-1,FD2000-1,FD2000-2,FD2000-3,SD2026,FV2006-1, FV2026-M,FB1026,FB2026,FB2026-M,FB2026-F,FD2020-1,FD2020-F.
Known Issues	<ol style="list-style-type: none"> 1. AndroidViewer will show connection failed when user changed the RTSP path setting of IP camera. 2. IP camera port number should be refer to the RTSP port number of IP camera (default is 554), but SF2012 and SF2111 series default is 80. 3. 2-way audio function in live view mode only supports IWH3216 , E5016(H), E1008(H) and P5036(H). 4. If mobile memory buffer is limited, user might encounter delayed audio when using 2-way audio function. 5. When the WiFi or 3G signal is weak or NVR/IP camera is busy,



Release Notes

Product

AndroidViewerHD

AndroidViewer can't search total devices in LAN when using NVR/IP camera search function.

6. AndroidViewer didn't support customized Android version (like Samsung S3 SPH-L710 4.4.2 Sprint Version).

Others

N/A



Release Notes

Product	AndroidViewerHD
Version	5.3.1022.27
Introduction	Official Release
Hardware Compatibility	Android system Mobile, PAD
Operating Systems	Android 2.3.5 above
Compatibility List	<ol style="list-style-type: none"> 1. NVR/DVR: E, P series, IWH series, EH series, NV series 2. Camera: SF2121H-R, SF2121H-BHR, SF2121H-DVR, FB2027-1/(E), FB2027-2,FB2027-3/(E), FB3027, FB2028-T1/(E), FB2028-T2/(E), FB2028-TM/(E), FV2028-T/(E),FV2028-TM/(E), FX2000/(E), FB3028-RT1/(E), FB3028-RT2/(E), FB3028-RTM/(E), FD2020/(E), FD2020-M/(E), FD3020, FD3020-M, FV2028/(E), FV3028, FV3028-RT/(E), FV3028-RTM/(E), FX3000-R/(E), SF2012H, SF2012H-B, SF2012H-C, SF2012H-D, SF2012H-DV, SF2111H-BR, SF2111H-DR, SF2111H-DVR, SF2111H-R, FV1306, FV2006, FC1320-P, FC1320-PW, FC2020-P, FC2020-PW, SD1306, FD1020, FC1020-P, FC2020-P1
Change Log	<ol style="list-style-type: none"> 1. Support Android 5.0 version. 2. Support 2nd stream display in live view mode.
Known Issues	<ol style="list-style-type: none"> 1. AndroidViewer will show connection failed when user changed the RTSP path setting of IP camera. 2. IP camera port number should be refer to the RTSP port number of IP camera (default is 554), but SF2012 and SF2111 series default is 80. 3. 2-way audio function in live view mode only supports IWH3216 , E5016(H), E1008(H) and P5036(H). 4. If mobile memory buffer is limited, user might encounter delayed audio when using 2-way audio function. 5. When the WiFi or 3G signal is weak or NVR/IP camera is busy, AndroidViewer can't search total devices in LAN when using NVR/IP camera search function. 6. AndroidViewer didn't support customized Android version (like Samsung S3 SPH-L710 4.4.2 Sprint Version).
Others	N/A



Release Notes

Product	AndroidViewerHD
Version	5.3.1022.26
Introduction	Official Release
Hardware Compatibility	Android system Mobile, PAD
Operating Systems	Android 2.3.5 above (except Android 5.0)
Compatibility List	<ol style="list-style-type: none"> Camera: SF2121H-R, SF2121H-BHR, SF2121H-DVR, FB2027-1/(E), FB2027-2,FB2027-3/(E), FB3027, FB2028-T1/(E), FB2028-T2/(E), FB2028-TM/(E), FV2028-T/(E),FV2028-TM/(E), FX2000/(E), FB3028-RT1/(E), FB3028-RT2/(E), FB3028-RTM/(E), FD2020/(E), FD2020-M/(E), FD3020, FD3020-M, FV2028/(E), FV3028, FV3028-RT/(E), FV3028-RTM/(E), FX3000-R/(E), SF2012H, SF2012H-B, SF2012H-C, SF2012H-D, SF2012H-DV, SF2111H-BR, SF2111H-DR, SF2111H-DVR, SF2111H-R, FV1306, FV2006, FC1320-P, FC1320-PW, FC2020-P, FC2020-PW, SD1306, FD1020, FC1020-P, FC2020-P1,FC1000,FC1000-1,FD2000-1,FD2000-2,FD2000-3,SD2026, FV2006-1,FV2026-M,FB1026,FB2026,FB2026-M,FB2026-F,FD2020-1, FD2020-F.
Change Log	<ol style="list-style-type: none"> Revise Android system support list, current version didn't support Android 5.0.
Known Issues	<ol style="list-style-type: none"> AndroidViewer will show connection failed when user changed the RTSP path setting of IP camera. IP camera port number should be refer to the RTSP port number of IP camera (default is 554), but SF2012 and SF2111 series default is 80. 2-way audio function in live view mode only supports IWH3216 , E5016(H), E1008(H) and P5036(H). If mobile memory buffer is limited, user might encounter delayed audio when using 2-way audio function. When the WiFi or 3G signal is weak or NVR/IP camera is busy, AndroidViewer can't search total devices in LAN when using NVR/IP camera search function. AndroidViewer didn't support customized Android version (like



Release Notes

Product	AndroidViewerHD
	(Samsung S3 SPH-L710 4.4.2 Sprint Version).
Others	N/A



Release Notes

Product	AndroidViewerHD
Version	5.3.1022.25
Introduction	Official Release
Hardware Compatibility	Android system Mobile, PAD
Operating Systems	Android 2.3.5 above
Compatibility List	<ol style="list-style-type: none">1. NVR/DVR: E, P series, IWH series, EH series, NV series2. Camera: SF2121H-R, SF2121H-BHR, SF2121H-DVR, FB2027-1/(E), FB2027-2,FB2027-3/(E), FB3027, FB2028-T1/(E), FB2028-T2/(E), FB2028-TM/(E), FV2028-T/(E),FV2028-TM/(E), FX2000/(E), FB3028-RT1/(E), FB3028-RT2/(E), FB3028-RTM/(E), FD2020/(E), FD2020-M/(E), FD3020, FD3020-M, FV2028/(E), FV3028, FV3028-RT/(E), FV3028-RTM/(E), FX3000-R/(E), SF2012H, SF2012H-B, SF2012H-C, SF2012H-D, SF2012H-DV, SF2111H-BR, SF2111H-DR, SF2111H-DVR, SF2111H-R, FV1306, FV2006, FC1320-P, FC1320-PW, FC2020-P, FC2020-PW, SD1306, FD1020, FC1020-P, FC2020-P1
Change Log	<ol style="list-style-type: none">1. Increase NVR list number up to 1024.2. Fixed 2-way audio bug when using DDNS on NV series platform.
Known Issues	<ol style="list-style-type: none">1. AndroidViewer will show connection failed when user changed the RTSP path setting of IP camera.2. IP camera port number should be refer to the RTSP port number of IP camera (default is 554), but SF2012 and SF2111 series default is 80.3. 2-way audio function in live view mode only supports IWH3216 , E5016(H), E1008(H) and P5036(H).4. If mobile memory buffer is limited, user might encounter delayed audio when using 2-way audio function.5. When the WiFi or 3G signal is weak or NVR/IP camera is busy, AndroidViewer can't search total devices in LAN when using NVR/IP camera search function.6. AndroidViewer didn't support customized Android version (like Samsung S3 SPH-L710 4.4.2 Sprint Version).
Others	N/A



Release Notes

Product	AndroidViewerHD
Version	5.3.1019.22
Introduction	Official Release
Hardware Compatibility	Android system Mobile, PAD
Operating Systems	Android 2.3.5 above
Compatibility List	<ol style="list-style-type: none">1. NVR/DVR: E, P series, IWH series, EH series, NV series2. Camera: SF2121H-R, SF2121H-BHR, SF2121H-DVR, FB2027-1/(E), FB2027-2,FB2027-3/(E), FB3027, FB2028-T1/(E), FB2028-T2/(E), FB2028-TM/(E), FV2028-T/(E),FV2028-TM/(E), FX2000/(E), FB3028-RT1/(E), FB3028-RT2/(E), FB3028-RTM/(E), FD2020/(E), FD2020-M/(E), FD3020, FD3020-M, FV2028/(E), FV3028, FV3028-RT/(E), FV3028-RTM/(E), FX3000-R/(E), SF2012H, SF2012H-B, SF2012H-C, SF2012H-D, SF2012H-DV, SF2111H-BR, SF2111H-DR, SF2111H-DVR, SF2111H-R, FV1306, FV2006, FC1320-P, FC1320-PW, FC2020-P, FC2020-PW, SD1306, FD1020, FC1020-P, FC2020-P1
Change Log	<ol style="list-style-type: none">1. Support AVer NVR P5036-R, P5036-16-R2. Remove AndroidViewer on Google play, AndroidViewer HD is suitable both for Mobile and PAD platform.
Known Issues	<ol style="list-style-type: none">1. AndroidViewer will show connection failed when user changed the RTSP path setting of IP camera.2. IP camera port number should be refer to the RTSP port number of IP camera (default is 554), but SF2012 and SF2111 series default is 80.3. 2-way audio function in live view mode only supports IWH3216 , E5016(H), E1008(H) and P5036(H).4. If mobile memory buffer is limited, user might encounter delayed audio when using 2-way audio function.5. When the WiFi or 3G signal is weak or NVR/IP camera is busy, AndroidViewer can't search total devices in LAN when using NVR/IP camera search function.6. AndroidViewer didn't support customized Android version (like Samsung S3 SPH-L710 4.4.2 Sprint Version).



Release Notes

Product AndroidViewerHD

Others N/A



Release Notes

Product	AndroidViewerHD
Version	5.3.1017.19
Introduction	Official Release
Hardware Compatibility	Android system Mobile
Operating Systems	Android 2.3.5 above
Compatibility List	<ol style="list-style-type: none"> 1. NVR/DVR: E series, IWH series, EH series, NV series 2. Camera: SF2121H-R, SF2121H-BHR, SF2121H-DVR, FB2027-1/(E), FB2027-2,FB2027-3/(E), FB3027, FB2028-T1/(E), FB2028-T2/(E), FB2028-TM/(E), FV2028-T/(E),FV2028-TM/(E), FX2000/(E), FB3028-RT1/(E), FB3028-RT2/(E), FB3028-RTM/(E), FD2020/(E), FD2020-M/(E), FD3020, FD3020-M, FV2028/(E), FV3028, FV3028-RT/(E), FV3028-RTM/(E), FX3000-R/(E), SF2012H, SF2012H-B, SF2012H-C, SF2012H-D, SF2012H-DV, SF2111H-BR, SF2111H-DR, SF2111H-DVR, SF2111H-R, FV1306, FV2006, FC1320-P, FC1320-PW, FC2020-P, FC2020-PW, SD1306, FD1020, FC1020-P, FC2020-P1
Change Log	<ol style="list-style-type: none"> 1. Increase camera list number to 1024. 2. Support AVer IP camera: FD1020, FC1020-P, FC2020-P1
Known Issues	<ol style="list-style-type: none"> 1. AndroidViewer will show connection failed when user changed the RTSP path setting of IP camera. 2. IP camera port number should be refer to the RTSP port number of IP camera (default is 554), but SF2012 and SF2111 series default is 80. 3. 2-way audio function in live view mode only supports IWH3216 , E5016 and E5016H. 4. If mobile memory buffer is limited, user might encounter delayed audio when using 2-way audio function. 5. When the WiFi or 3G signal is weak or NVR/IP camera is busy, AndroidViewer can't search total devices in LAN when using NVR/IP camera search function. 6. AndroidViewer didn't support customized Android version (like Samsung S3 SPH-L710 4.4.2 Sprint Version).
Others	N/A



Release Notes

Product	AndroidViewerHD
Version	5.3.1016.17
Introduction	Official Release
Hardware Compatibility	Android system Mobile
Operating Systems	Android 2.3.5 above
Compatibility List	<ol style="list-style-type: none">1. NVR/DVR: E series, IWH series, EH series, NV series2. Camera: SF2121H-R, SF2121H-BHR, SF2121H-DVR, FB2027-1/(E), FB2027-2,FB2027-3/(E), FB3027, FB2028-T1/(E), FB2028-T2/(E), FB2028-TM/(E), FV2028-T/(E),FV2028-TM/(E), FX2000/(E), FB3028-RT1/(E), FB3028-RT2/(E), FB3028-RTM/(E), FD2020/(E), FD2020-M/(E), FD3020, FD3020-M, FV2028/(E), FV3028, FV3028-RT/(E), FV3028-RTM/(E), FX3000-R/(E), SF2012H, SF2012H-B, SF2012H-C, SF2012H-D, SF2012H-DV, SF2111H-BR, SF2111H-DR, SF2111H-DVR, SF2111H-R, FV1306, FV2006, FC1320-P, FC1320-PW, FC2020-P, FC2020-PW, SD1306
Change Log	<ol style="list-style-type: none">1. Bug fixed: H.264 codec compatibility issue on NV series platform.
Known Issues	<ol style="list-style-type: none">1. AndroidViewer will show connection failed when user changed the RTSP path setting of IP camera.2. IP camera port number should be refer to the RTSP port number of IP camera (default is 554), but SF2012 and SF2111 series default is 80.3. 2-way audio function in live view mode only supports IWH3216 , E5016 and E5016H.4. If mobile buffer is limited, user might encounter delayed audio when using 2-way audio function.5. When the WiFi or 3G signal is weak or NVR/IP camera is busy, AndroidViewer can't search total devices in LAN when using NVR/IP camera search function.
Others	N/A



Release Notes

Product	AndroidViewerHD
Version	5.3.1013.16
Introduction	Official Release
Hardware Compatibility	Android system Mobile
Operating Systems	Android 2.3.5 above
Compatibility List	<ol style="list-style-type: none"> 1. NVR/DVR: E series, IWH series, EH series, NV series 2. Camera: SF2121H-R, SF2121H-BHR, SF2121H-DVR, FB2027-1/(E), FB2027-2,FB2027-3/(E), FB3027, FB2028-T1/(E), FB2028-T2/(E), FB2028-TM/(E), FV2028-T/(E),FV2028-TM/(E), FX2000/(E), FB3028-RT1/(E), FB3028-RT2/(E), FB3028-RTM/(E), FD2020/(E), FD2020-M/(E), FD3020, FD3020-M, FV2028/(E), FV3028, FV3028-RT/(E), FV3028-RTM/(E), FX3000-R/(E), SF2012H, SF2012H-B, SF2012H-C, SF2012H-D, SF2012H-DV, SF2111H-BR, SF2111H-DR, SF2111H-DVR, SF2111H-R, FV1306, FV2006, FC1320-P, FC1320-PW, FC2020-P, FC2020-PW, SD1306
Change Log	<p>New Feature:</p> <ol style="list-style-type: none"> 1. Support 2-way audio for E5016 and E5016H 2. Support analog camera PTZ setting
Known Issues	<ol style="list-style-type: none"> 1. AndroidViewer will show connection failed when user changed the RTSP path setting of IP camera. 2. IP camera port number should be refer to the RTSP port number of IP camera (default is 554), but SF2012 and SF2111 series default is 80. 3. 2-way audio function in live view mode only supports IWH3216 , E5016 and E5016H. 4. If mobile buffer is limited, user might encounter delayed audio when using 2-way audio function. 5. When the WiFi or 3G signal is weak or NVR/IP camera is busy, AndroidViewer can't search total devices in LAN when using NVR/IP camera search function.



Release Notes

Product	AndroidViewerHD
	6. AndroidViewer can't decode h.264 codec when connect to NV series DVR.
Others	N/A



Release Notes

Product	AndroidViewerHD
Version	5.1.109.13
Introduction	Official Release
Hardware Compatibility	Android system Mobile
Operating Systems	Android 2.3.5 above
Compatibility List	<ol style="list-style-type: none">1. NVR/DVR: E series, IWH series, EH series, NV series2. Camera: SF2121H-R, SF2121H-BHR, SF2121H-DVR, FB2027-1/(E), FB2027-2,FB2027-3/(E), FB3027, FB2028-T1/(E), FB2028-T2/(E), FB2028-TM/(E), FV2028-T/(E),FV2028-TM/(E), FX2000/(E), FB3028-RT1/(E), FB3028-RT2/(E), FB3028-RTM/(E), FD2020/(E), FD2020-M/(E), FD3020, FD3020-M, FV2028/(E), FV3028, FV3028-RT/(E), FV3028-RTM/(E), FX3000-R/(E), SF2012H, SF2012H-B, SF2012H-C, SF2012H-D, SF2012H-DV, SF2111H-BR, SF2111H-DR, SF2111H-DVR, SF2111H-R, FV1306, FV2006, FC1320-P, FC1320-PW, FC2020-P, FC2020-PW, SD1306
Change Log	<p>New Feature for E-series NVR</p> <ol style="list-style-type: none">1. Support auto-search NVR/IP Camera2. Support event search in playback mode3. Show NVR health status4. Show POS information <p>Improvement:</p> <ol style="list-style-type: none">3. Support digit-PTZ in live view and playback mode4. Bug fixed
Known Issues	<ol style="list-style-type: none">1. IP camera will show connection failed when user change the RTSP path setting.2. When setting IP camera, the port number should be refer to the RTSP port number of IP camera (default is 554) except SF2012 and SF2111 series (default is 80).3. 2-way audio function in live view mode only supports IWH3216.4. AndroidViewer doesn't support PTZ function with analog camera.5. POS information only support playback mode in this version.



Release Notes

Product

AndroidViewerHD

6. When the WiFi signal is weak or NVR/IP Camera is too busy, AndroidViewer can't search total devices in LAN when using NVR/IPCam search function.

Others

N/A



Release Notes

Product	AndroidViewerHD
Version	4.5.106.7
Introduction	3 th Official Release
Hardware Compatibility	Android system Mobile
Operating Systems	Android 2.3.5 above
Compatibility List	<ol style="list-style-type: none">1. NVR: Full range of AVer NVRs/DVR2. Camera: SF2121H-R, SF2121H-BHR, SF2121H-DVR, FB2027-1, FB2027-2,FB2027-3, FB3027, FB2028-T1, FB2028-T2, FB2028-TM, FV2028-T,FV2028-TM, FX2000, FB3028-RT1, FB3028-RT2, FB3028-RTM, FD2020, FD2020-M, FD3020, FD3020-M, FV2028, FV3028, FV3028-RT, FV3028-RTM, FX3000-R, SF2012H, SF2012H-B, SF2012H-C, SF2012H-D, SF2012H-DV, SF2111H-BR, SF2111H-DR, SF2111H-DVR, SF2111H-R
Change Log	<ol style="list-style-type: none">1. Support AVer EOL product (NV series, EB series).
Known Issues	<ol style="list-style-type: none">1. When the internet connection is unstable or 3G signal is weak, live view image maybe broken or lost.
Others	N/A



Release Notes

Product	AndroidViewerHD
Version	4.7.107.9
Introduction	Official Release
Hardware Compatibility	Android system Mobile
Operating Systems	Android 2.3.5 above
Compatibility List	<ol style="list-style-type: none">1. NVR: Full range of AVER NVRs/DVR2. Camera: SF2121H-R, SF2121H-BHR, SF2121H-DVR, FB2027-1, FB2027-2,FB2027-3, FB3027, FB2028-T1, FB2028-T2, FB2028-TM, FV2028-T,FV2028-TM, FX2000, FB3028-RT1, FB3028-RT2, FB3028-RTM, FD2020, FD2020-M, FD3020, FD3020-M, FV2028, FV3028, FV3028-RT, FV3028-RTM, FX3000-R, SF2012H, SF2012H-B, SF2012H-C, SF2012H-D, SF2012H-DV, SF2111H-BR, SF2111H-DR, SF2111H-DVR, SF2111H-R, FV1306, FV2006, FC1320-P, FC1320-PW, FC2020-P, FC2020-PW, SD1306
Change Log	<ol style="list-style-type: none">1. Support more camera model
Known Issues	<ol style="list-style-type: none">1. IP camera will connection failed when user change the RTSP path setting from IP camera's web UI.2. When setting IP camera, the port number should be refer to the RTSP port number of IP camera.3. 2-way audio function in live view mode only supports for IWH3216.
Others	N/A



Release Notes

Product	AndroidViewerHD
Version	4.5.106.7
Introduction	3 th Official Release
Hardware Compatibility	Android system Mobile
Operating Systems	Android 2.3.5 above
Compatibility List	<ol style="list-style-type: none">1. NVR: Full range of AVer NVRs/DVR2. Camera: SF2121H-R, SF2121H-BHR, SF2121H-DVR, FB2027-1, FB2027-2,FB2027-3, FB3027, FB2028-T1, FB2028-T2, FB2028-TM, FV2028-T,FV2028-TM, FX2000, FB3028-RT1, FB3028-RT2, FB3028-RTM, FD2020, FD2020-M, FD3020, FD3020-M, FV2028, FV3028, FV3028-RT, FV3028-RTM, FX3000-R, SF2012H, SF2012H-B, SF2012H-C, SF2012H-D, SF2012H-DV, SF2111H-BR, SF2111H-DR, SF2111H-DVR, SF2111H-R
Change Log	<ol style="list-style-type: none">1. Support AVer EOL product (NV series, EB series).
Known Issues	<ol style="list-style-type: none">1. When the internet connection is unstable or 3G signal is weak, live view image maybe broken or lost.
Others	N/A

Ps The latest update should be listed on the top



Release Notes

Product	AndroidViewerHD
Version	4.3.104.6
Introduction	2 nd Official Release
Hardware Compatibility	Android system Mobile
Operating Systems	Android 2.3.5 above
Compatibility List	<ol style="list-style-type: none">1. NVR: Full range of AVER NVRs/DVR (except EOL product)2. Camera: SF2121H-R, SF2121H-BHR, SF2121H-DVR, FB2027-1, FB2027-2,FB2027-3, FB3027, FB2028-T1, FB2028-T2, FB2028-TM, FV2028-T,FV2028-TM, FX2000, FB3028-RT1, FB3028-RT2, FB3028-RTM, FD2020, FD2020-M, FD3020, FD3020-M, FV2028, FV3028, FV3028-RT, FV3028-RTM, FX3000-R, SF2012H, SF2012H-B, SF2012H-C, SF2012H-D, SF2012H-DV, SF2111H-BR, SF2111H-DR, SF2111H-DVR, SF2111H-R
Change Log	<ol style="list-style-type: none">1. New user interface with new process2. Customized login password checking method3. Support new camera module (Aver homemade)4. Remove slide feature in live view mode.
Known Issues	<ol style="list-style-type: none">1. When the internet connection is unstable or 3G signal is weak, live view image maybe broken or lost.
Others	N/A

Ps The latest update should be listed on the top



Release Notes

Product	AndroidViewerHD
Version	4.1.100.4
Introduction	1 st Official Release
Hardware Compatibility	Android system Mobile
Operating Systems	Android 2.3.5 above
Compatibility List	NVR: Full range of AVER NVRs/DVRs Camera: SF2012H, SF2012H-B, SF2012H-C, SF2012H-D, SF2012H-DV, SF2111H-BR, SF2111H-DR, SF2111H-DVR, SF2111H-R
Change Log	N/A
Known Issues	N/A
Others	N/A

